





FIG.









Reply to NFMP dated: January 30, 2004 Replacement Sheet





Reply to NFMP dated: January 30, 2004



- 72 LOCAL MAINTENANCE KEYBOARD PROVIDER DISPLAY S 9 **EXPECTANCY DETERMINATION PREPARATION** 989 65 EMAIL REQUEST UNIT UNIT GRAPH ,646 FIN PRIOR DATA 671 EMBEDDING **PREDICTION** REQUEST FIG. 8 63 69 LINO LIND UNIT 611 .99 STORAGE RETRIEVAL 62 LINO UNIT 9 RECEPTION HOSPITAL A PROCESSOR **APPARATUS** - PC -**(EYBOARD**

SERVICE

C

DISPLAY

416-

UNIT




FIG. 9

(i. 3




FIG. 10




FIG. 11




FIG. 12A




FIG. 12B

Reply to NFMP dated: January 30, 2004




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15A




FIG. 15B

ABNORMALITY LEVEL	CONTRACT 1	CONTRACT 2
	HIGH AMOUNT LOW RISK	REASONABLE SOME RISK
HIGH	REPLACEMENT (URGENT)	REPLACEMENT (URGENT)
MEDIUM	REPLACEMENT (IN REGULAR MAINTENANCE)	REPLACEMENT (IN REGULAR MAINTENANCE)
LOW	REPLACEMENT (IN REGULAR MAINTENANCE)	
NORMAL		

FIG. 16




FIG. 17

Reply to NFMP dated: January 30, 2004




FIG. 18






FIG. 19

Reply to NFMP dated: January 30, 2004 Replacement Sheet





Reply to NFMP dated: January 30, 2004

Replacement Sheet

START **PHOTOELECTRIC** 2201-**CONVERSION** PREAMPLIFICATION 2202-NO BIAS VOLTAGE - 2204 BIAS VOLTAGE 2203 ≧THRESHOLD CORRECTION YES 2205 **ALARM** LIMITING 2206 **AMPLIFICATION** AMPLITUDE VOLTAGE NO - 2208 AMPLITUDE VOLTAGE 2207 CORRECTION ≧THRESHOLD

2209

ALARM

FIG. 22

YES

END

المأ فيها عا

OBLON, SPIVAK, et al Docket No:243643US2TTC Inventor: Yuuji SAWANAGA, et al Serial No: 10/686,705 Reply to NFMP dated: January 30, 2004




FIG. 23